


MAGNA CLAW


Model J20037

- 1 Weld Magna Wire to damaged area using instructions provided with your Magna-Spot Stud Welder Kit.



- 2 Drag Magna Claw fingers across panel and hook under Magna wire as shown.

PULL



- 3 Remove dent by gradually working Magna Claw over length of crease. Pull until all fingers are even.



- 4 Disengage Magna Claw from wire and complete repair.

MOTOR GUARD